Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

BJ311 SANITATION GARAGE NY Spills S108957158
WSW 2012 NEPTUNE AVE N/A

1/4-1/2 0.481 mi.

2541 ft. Site 1 of 3 in cluster BJ

NEW YORK, NY

 Relative:
 SPILLS:

 Higher
 Name:
 SANITATION GARAGE

 Actual:
 Address:
 2012 NEPTUNE AVE

 1 ft.
 City,State,Zip:
 NEW YORK, NY

 Spill Number/Closed Date:
 0709366 / 2007-12-12

Facility ID: 0709366

 Facility Type:
 ER

 DER Facility ID:
 340032

 Site ID:
 390435

 DEC Region:
 2

 Spill Cause:
 Unknown

Spill Class: C4
SWIS: 2401
Spill Date: 2007-11-29
Investigator: SFRAHMAN
Referred To: Not reported
Reported to Dept: 2007-11-29
CID: 444
Water Affected: Net reported

Water Affected: Not reported Spill Source: Unknown Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** Not reported

Remediation Phase: 0

Date Entered In Computer: 2007-11-29
Spill Record Last Update: 2007-12-12
Spiller Name: JAY SHAH

Spiller Company: SANITATION GARAGE Spiller Address: 2012 NEPTUNE AVE

Spiller Company: 999
Contact Name: JAY SHAH

DEC Memo: "11/29/07-Hiralkumar Patel, spoke with Mr. Mignone at NYC sanitation.

site has 4000 gal double wall UST. during oil delivery, cap on riser was missing and oil came out from riser inside sump and between two

walls of tank. no spill on room surface or soil. as oil filled in space between tank walls, alarm went off and delivery stopped. oil contained. will do tank test. all under control. Al Mignone Ph. (646) 235-3183 12/03/07-Hiralkumar Patel. received call from Al. they has scheduled tank test on tomorrow. 12/12/07 I spoke with Jay Shah of

Sanitation Dept. A.B Oil cleaned the oil from the interstitial space. Waste disposal manifest to come .(SR)"

"IN PROCESS OF CLEANING UP"

Remarks:
All Materials:

 Site ID:
 390435

 Operable Unit ID:
 1147538

 Operable Unit:
 01

 Material ID:
 2137970

 Material Code:
 0001A

 Material Name:
 #2 fuel oil

 Case No.:
 Not reported

Map ID
Direction
Distance
Elevation

Site

MAP FINDINGS

EDR ID Number
Database(s) EPA ID Number

Material FA: Petroleum Quantity: 60.00 Units: G Recovered: .00

Oxygenate: Not reported